

Shallow Hydrofracturing to Enhance Solvent Recovery

Robert Healy, E. Matt Germon, Randy Pratt CH2M Hill

> John P. Gross, Glen M. Wyatt Weyerhaeuser Company






Aquitard Remediation Using Hydrofracturing and Vacuum-Enhanced Extraction

Phased approach

- April 2001 Hydrofracturing Pilot Study
- October 2001 Full Scale Hydrofracturing
- April 2002 Interim Aquitard Extraction System
- April 2003 Full Scale Aquitard Extraction System

Hydrofracture Pilot Study



Drill Rig at HF-1




Open Borehole at HF-1






Double-Packer Setup





HF-1 Lower Interval




Surface Cracks From Hydrofracturing HF-1 Lower Interval









Subsurface Fracture




Drilling HF-2 Borehole




Installing
Packer in
HF-2
Borehole




HF-2 Lower Interval



HF-2 Upper Interval




Well Yield Comparison




Pilot Test Conclusions

- Based on the Flow vs Pressure Plots, hydrofracturing looked promising
- Flow rate testing results created uncertainty concerning the long-term effectiveness of the fractures
- Decided that propant was required for full scale application

Proposed Fractured Well Locations






Notching to induce horizontal fracturing


Propant - Mixture of Guar Gel and Sand

- Guar Gel
 - Organic powder thickener
 - Completely soluble in hot and cold water
- Sand
 - -20/50 mesh
- Borax
 - Used as an enzyme to break down the guar gel
 24- to 48-hours after injection





Water Level Response to Hydrofracturing



Full Scale Aquitard Hydrofracturing Conclusions

- 18 fractures were completed
- Did they result in horizontal or vertical fractures?
- How effective are the fractures?
- Will they stay open?
- Decided to connect only a subset of the wells to the existing treatment system, to evaluate the effectiveness of the hydrofracturing

Interim Aquitard Extraction System - Installed April 2002

| | Groundwater Extraction Rates |
|-------------------------|------------------------------|
| | 8/26 thru 10/17 |
| Extraction Wells | gpm |
| E-22 | 0.37 |
| E-33 | 0.15 |
| E-03 | 0.20 |
| E-32 | 0.15 |
| E-21 | 0.41 |
| E-11 | 0.56 |
| Aquitard Average | 0.31 |
| Aquitard Total | 1.84 |
| Aquifer | 10.76 |

Conclusions

- Hydrofractured wells averaged ~0.3 gpm
- Recovered approximately the same amount of contaminants from the Aquitard as we did from the Aquifer and Perched Zone
- The propagation patterns of the fractures is unclear